



AMERICAN EMERGENCY VEHICLES

September 23, 2014

MOBILE LIFE SUPPORT
69 DICKSON ST
NEWBURGH, NY 12550

Recently GM Chassis Upfitters have received GM Advisory Bulletin (UIB #117) concerning Chassis Block Heater Usage.

General Motors has issued an Upfitter Integration Bulletin dated July 16, 2014 (see attachment). The subject of the bulletin is titled Improper Engine Block Heater (Option K05) Continuous Power. GM states that the engine block heaters should not be tied into any circuit that could activate the engine block heater unless the outside temperature is between -18 degrees and -29 degrees C and should not to be continuously plugged into an "A/C" source.

We want to make sure our customers know about this bulletin and provide guidance on how to insure vehicles in their fleets can be quickly and simply modified to comply with the General Motors guidelines.

Step 1) Raise the hood and locate the 115 volt male and female electrical plugs
Reference Photo #1

Step 2) Disconnect / unplug the male and female connectors. Reference Photo #2

Step 3) Recommend placing an outlet plug protector into the female receptacle

Thank you for your business if you have any questions please contact us.

Dominick Gaetano Jr.
Warranty Administrator
800-374-9749

AEV-SA140915