



Mercedes-Benz
The best or nothing.

star bulletin



Date: August 11, 2014
Order No.: P-B-54.10/265
Group: 54

**SUBJECT: MY-All, Model 205 without Code U98 Lithium-Ion Starter Battery
Resetting the Starter Battery Charge Throughput Counter**

With modifications to the energy management system, it is essential to reset the charge throughput of the starter battery using Xentry DAS each time the starter battery is replaced.

Replacement of the starter battery is performed in the front SAM control unit (N10/6) under the menu item "Actuations".

Operation Codes:

- 54-1109 Check condition of battery Terminal stamp: Batt. part no.:Test code:
- 54-1011 Conduct quick test
- 54-1126 Replace battery (after check)

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.

© 2014 Mercedes-Benz USA, LLC.
Mercedes-Benz Canada, Inc.
Dealer Workshop Services
www.MBUSA.com
www.startekinfo.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A.
1-800-FOR-MERCEdes