



Mercedes-Benz

The best or nothing.

**star bulletin**



Date: July 1, 2014  
Order No.: P-B-68.30/84  
Group: 68

**SUBJECT: MY-AII, Model 217  
Installing Door Sill Retaining Clips**

Retaining clips become detached when the door sill is removed. When reinstalling the retaining clips make sure they are attached in the correction position or the electrical wiring harness under the sill could become damaged.

Reference WIS document AR68.30-P-4100LC Remove/install door sill molding.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.

© 2014 Mercedes-Benz USA, LLC.  
Mercedes-Benz Canada, Inc.  
Dealer Workshop Services  
[www.MBUSA.com](http://www.MBUSA.com)  
[www.startekinfo.com](http://www.startekinfo.com)

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A.  
1-800-FOR-MERCEdes