



Mercedes-Benz
The best or nothing.

star bulletin



Date: November 20, 2014
Order No.: P-B-72.20/118
Group: 72

SUBJECT: MY-All, Model 156 with Code 890 Easy-Pack-Tailgate
Lifegate Control Drive Unit

Since 2/2014 vehicles with code 805 and 056 have a new factory-installed drive unit with Hall sensor A 156 890 02 30. Upon inventory depletion of this old drive unit with position sensor A 156 890 01 30, only the new drive unit with Hall sensor will be available.

When installing the new drive unit in vehicles with code 804 or code 805 and without code 055, the previous gas-filled strut A 156 980 05 64 must be replaced by the new gas-filled strut A 156 980 07 64.

Code 980, if not yet available, must also be entered in the vehicle data card online in the VeDoc.

An SCN coding of the control unit for the trunk lid/liftgate control (N121/1) must then be performed.

Parts Information

Qty.	Part Name	Part Number
1	New Lifegate Control Drive Unit with Hall sensor	A 156 890 02 30

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Records.

© 2014 Mercedes-Benz USA, LLC.
Mercedes-Benz Canada, Inc.
Dealer Workshop Services
www.MBUSA.com
www.startekinfo.com

All rights reserved. Reproduction or translation in whole or in part is not permitted without authorization from the publisher. Printed in U.S.A.
1-800-FOR-MERCEdes