



Date: January 3, 2014  
Order No.: V-B-32.25/02  
Group: 32

**SUBJECT: MY-All, Models, 903, 904, and 906**  
**Check Shock Absorbers**

Please do not replace any shock absorbers without performing the following test procedures.

**Test Procedures in WIS**

Notes on shock absorber testing, AH32.25-N-0001-01A

Check shock absorbers for leaks AR32.25-W-0121-02A

Check shock absorbers for damage AR32.25-W-0121-01A

**NOTE:** If the issues described in TIPS for group 32 apply to model 906, the shock absorbers should be replaced in pairs. Also replace shock absorbers in pairs for any model with mileage above 95,000 miles.

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.