



TECH TIP: Issues with Eco Gauge Needle

NUMBER: TT039

MODEL: Optima Hybrid (All)

DATE: 01/13/2014

Symptom: The ECO gauge needle never reaches the green shaded portion of the cluster, even on wide open throttle. No codes are stored and all modules communicate.

Repair: Perform the brake pedal travel sensor calibration – Listed as PTS calibration in the S/W management section of the “Active Hydraulic Brake” (AHB) system.

Note: Tech Tips are not a substitute for proper diagnosis.