

Subject

Market

Blower Motor Only Operates on High**USA**

Service Category

Vehicle Interior

Section

Heating/Air Conditioning

Applicability

2014MY Tacoma**APPLICABLE VEHICLES**

2014

Tacoma

CONDITION

Some 2014 model year Tacoma vehicles may exhibit a condition where the blower motor only operates on High Speed and all other blower speeds are inoperative.

RECOMMENDATIONS

If this condition is found, remove the blower motor resistor to verify the blower motor resistor fuse is intact and **NOT** open/blown.

- Please create a TAS case and contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.
- When creating a TAS case, use the following case coding to ensure it is directed to the Electrical group:
 - Vehicle Interior + Heating/Air Conditioning + Fan/Blower/Air Flow + Abnormal Operation

LINK REFERENCES

This Tech Tip does not contain any link references