

Subject

Transaxle Whine Noise

Market

USA

Service Category

Drivetrain

Section

Automatic Transmission/Transaxle

Applicability

'10-'11 Camry U760**APPLICABLE VEHICLES**

2010-2011

Camry

CONDITION

Some 2010-2011 model year Camry vehicles equipped with a U760E transaxle may exhibit a whine noise most noticeable between 40-60 mph.

RECOMMENDATIONS

- This condition is currently under investigation.
- Please create a TAS case and contact TAS regarding any vehicle matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with a TAS Product Engineer.
- When creating a TAS case, use the following case coding to ensure it is directed to the Powertrain group:
Drivetrain + Automatic Transmission/Transaxle + Unknown + Noise-Abnormal

LINK REFERENCES

This Tech Tip does not contain any link references