
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Friday, May 30, 2014 6:25 PM
To:
Subject: Internal notification for: G_0000193040 Safety Bulletins 13454B, 14063B, 14092A, 14113C and 14133C - Parts and Warranty Information Sections Revised
Attachments: 13454B Bulletin.pdf; 14063B Bulletin.pdf; 14092A Bulletin.pdf; 14113C Bulletin.pdf; 14133C Bulletin.pdf

Date: 5/30/2014 Ref. number: Service / Field Action / G_0000193040
Subject: **Safety Bulletins 13454B, 14063B, 14092A, 14113C and 14133C - Parts and Warranty Information Sections Revised**

GM CUSTOMER CARE AND AFTERSALES
DCS3160
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 30, 2014

Subject: Safety Bulletins 13454B, 14063B, 14092A, 14113C and 14133C
Ignition Switch / Ignition Lock Cylinder / Ignition Key
Parts and Warranty Information Sections Revised

Models: 2005-2010 Chevrolet Cobalt
2006-2011 Chevrolet HHR
2006-2010 Pontiac Solstice
2005-2006 Pontiac Pursuit (Canada Only)
2007-2010 Pontiac G5
2003-2007 Saturn Ion
2007-2010 Saturn Sky

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

The Parts Information and Warranty Transaction Information sections have been revised. The ignition key images on the customer notice included in bulletins 14113C and 14133C have also been enhanced. Please provide this improved notice to customers. Please see the attached bulletins for details. Please discard all copies of bulletins 13454A, 14063A, 14092, 14113B and 14133B.

END OF MESSAGE