
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Saturday, January 18, 2014 11:39 AM
To: -----
Subject: Internal notification for: G_0000183610 Release From Stop Delivery - Service Update Bulletin 14016 - Incorrect Engine Control Module Calibration - Inventory Vehicles Only
Attachments: 14016 US Stock VIN List.xlsx; 14016 Bulletin.pdf

Date: 1/18/2014 Ref. number: Service / Field Action / G_0000183610
Subject: **Release From Stop Delivery - Service Update Bulletin 14016 - Incorrect Engine Control Module Calibration - Inventory Vehicles Only**

**GM CUSTOMER CARE AND AFTERSALES
DCS3121
URGENT - DISTRIBUTE IMMEDIATELY**

Date: January 18, 2014

Subject: Release From Stop Delivery - Service Update Bulletin 14016
Incorrect Engine Control Module Calibration
Inventory Vehicles Only

Models: 2014 Chevrolet Camaro Equipped with 3.6L Engine (LFX)
and 6 Speed Automatic Transmission (MYB)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

General Motors is announcing Service Update Bulletin 14016 today. The total number of U.S. vehicles involved is approximately 7,600. Please see the attached bulletin for details.

Vehicles involved in this service update were placed on stop delivery January 17, 2014. Once the service procedure contained this bulletin has been performed on the vehicle, the vehicle is released from stop delivery and can be delivered to the customer, dealer traded, or used for demonstration purposes.

Global Warranty Management (GWM)

The Investigate Vehicle History screen in GWM will be updated in the near future. A list of involved vehicles in dealer inventory is attached to this message.

Service Update Bulletin (SUB) Information Link