

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Wednesday, February 12, 2014 10:48 AM  
**To:**  
**Subject:** Internal notification for: G\_0000185345 13232A – Service Update Bulletin - Black Door Tape Cleaning / Replacement - Service Procedure Revised  
**Attachments:** 13232A Bulletin.pdf

---

Date: 2/12/2014 Ref. number: Service / Field Action / G\_0000185345  
Subject: **13232A – Service Update Bulletin - Black Door Tape Cleaning / Replacement - Service Procedure Revised**

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3135  
URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** February 12, 2014

**Subject:** 13232A – Service Update Bulletin  
Black Door Tape Cleaning / Replacement  
Service Procedure Revised

**Models:** 2013 Chevrolet Spark

**To:** All Chevrolet Dealers


**Attention:** General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

This bulletin has been revised to include additional information about the condition of the black tape. See the note at the beginning of the service procedure in the attached bulletin. Please discard all copies of bulletin 13232.

**END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES**

---

Message Attachment(s):

 [13232A Bulletin.pdf](#) Acrobat PDF (282.5KB)  
13232A Bulletin

---

Contact name:

Department: Service - Brand Quality

Phone:

Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator

Archives: 7/12/2014

Expires: 2/12/2015