

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Thursday, January 16, 2014 11:27 AM  
**To:** -----  
**Subject:** Internal notification for: G\_0000183454 13370A - Emission Recall - Fuel Pump Pressure Regulator Replacement - Revised  
**Attachments:** 13370A bulletin.pdf

---

Date: 1/16/2014 Ref. number: Service / Field Action / G\_0000183454  
Subject: **13370A - Emission Recall - Fuel Pump Pressure Regulator Replacement - Revised**

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3119  
URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** January 16, 2014

**Subject:** 13370A – Emission Recall  
Fuel Pump Pressure Regulator Replacement  
Revised Service Procedure

**Models:** 2014 Chevrolet Silverado 1500 and GMC Sierra 1500 Vehicles  
Equipped with 4.3L Engine (LV3) or 5.3L Engine (L83)

**To:** All Chevrolet and GMC Dealers


**Attention:** General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

Bulletin 13370A has been revised to modify Steps 5 and 6 in the service procedure. Please discard all copies of bulletin 13370.

**END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES**

---

Message Attachment(s):

 [13370A bulletin.pdf](#) Acrobat PDF (241.5KB)  
13370A bulletin

---

Contact name:	E-Mail:
Department: Service – Brand Quality	Phone:
Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator	