

---

**From:** gm\_gmssg\_q01 <nobody@gm.com>  
**Sent:** Wednesday, January 15, 2014 3:47 PM  
**To:** .....  
**Subject:** Internal notification for: G\_0000183391 14008A - Safety Recall - Overheated Exhaust Components - Customer Letter and Additional VINs Added  
**Attachments:** 14008A bulletin.pdf; 14008 Inventory VINs 1-15-14.xlsx

---

Date: 1/15/2014 Ref. number: Service / Field Action / G\_0000183391  
Subject: **14008A - Safety Recall - Overheated Exhaust Components - Customer Letter and Additional VINs Added**

---

**GM CUSTOMER CARE AND AFTERSALES  
DCS3118  
URGENT - DISTRIBUTE IMMEDIATELY**

**Date:** January 15, 2014

**Subject:** 14008A – Safety Recall  
Overheated Exhaust Components  
Customer Letter Added and Additional Vehicles Added

**Models:** 2014 Chevrolet Silverado 1500 and GMC Sierra 1500 Equipped  
with 4.3L Engine (LV1/LV3) or 5.3L Engine (L83)

**To:** All Chevrolet and GMC Dealers

**Attention:** General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
and Warranty Administrator

Bulletin 14008A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 14008.

Included with this message is a revised VIN list that includes additional vehicles.


**Customer Letter Mailing**

The customer letter mailing will begin on January 16, 2014.

**END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES**

---

Message Attachment(s):

 14008A bulletin.pdf Acrobat PDF (273.9KB)