


**From:**   
**Sent:** Tuesday, April 01, 2014 9:25 AM  
**To:**   
**Subject:** FW: Internal notification for: G\_0000188867 RPO UYS Radio Bulletin PI0285 Now Revised to PI0285D  
**Attachments:** RPO UYS Radio Bulletin PI0285 Now Revised to PI0285D.htm

**From:** gm\_gmssg\_q01 [mailto:nobody@gm.com]  
**Sent:** Tuesday, April 01, 2014 9:22 AM  
**To:**   
**Subject:** Internal notification for: G\_0000188867 RPO UYS Radio Bulletin PI0285 Now Revised to PI0285D



Date: 4/01/2014 Ref. number: Service / Service Operations / G\_0000188867  
 Subject: **RPO UYS Radio Bulletin PI0285 Now Revised to PI0285D**

GM CUSTOMER CARE & AFTERSALES  
URGENT - DISTRIBUTE IMMEDIATELY

DATE	31-March-2014
SUBJECT	RPO UYS Radio Bulletin PI0285 Now Revised to PI0285D
MODELS	2010-2011 Buick LaCrosse 2011 Buick Regal 2010-2011 Cadillac SRX 2010-2011 Chevrolet Equinox 2011 Chevrolet Cruze 2010-2011 GMC Terrain All Equipped with Navigation Radio RPO UYS
TO	All Chevrolet Dealers All Cadillac Dealers All Buick Dealers All GMC Dealers
ATTN	Service Advisor* Service Manager* Service Technician

UYS radio PI0285 is now revised to PI0285D with new Recommendation/Instructions to replace the radio for any of the referenced Condition/Concerns.

Thank you for your cooperation.

END OF MESSAGE  
GM CUSTOMER CARE & AFTERSALES

Contact name: E-Mail:   
 Department: Service - Brand Quality Phone: -   
 Intended roles: Service Advisor, Service Manager, Service Technician   
 Archives: 6/01/2014 Expires: 4/01/2015