
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Friday, February 28, 2014 5:31 AM
To:
Subject: Internal notification for: G_0000186341 14046 - Service Update - Goodwill for Repeat Tail Lamp Repair
Attachments: 14046 bulletin.pdf

Date: 2/28/2014 Ref. number: Service / Field Action / G_0000186341
Subject: **14046 - Service Update - Goodwill for Repeat Tail Lamp Repair**

**GM CUSTOMER CARE AND AFTERSALES
DCS3147
URGENT - DISTRIBUTE IMMEDIATELY**

Date: February 28, 2014

Subject: 14046 – Service Update Bulletin
Goodwill for Repeat Tail Lamp Repair

Models: 2014 Chevrolet Impala

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

General Motors is announcing Service Update Bulletin 14046 today. The total number of U.S. vehicles involved is 183. Please see the attached bulletin for details.

Global Warranty Management (GWM)


The “Investigate Vehicle History” (IVH) screen will be updated February 28, 2014.

Service Update Bulletin (SUB) Information Link

The SUB Information will not be loaded to GlobalConnect for this Service Update.

**END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES**

Message Attachment(s):

 14046 bulletin.pdf Acrobat PDF (102.3KB)
14046 bulletin

Contact name: