
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Tuesday, April 29, 2014 10:08 AM
To:
Subject: Internal notification for: G_0000190846 14134 – Service Update Bulletin - OBDII Noncompliance - Misfire Detection - Service Bulletin Attached
Attachments: 14134 Bulletin.pdf

Date: 4/29/2014 Ref. number: Service / Field Action / G_0000190846
Subject: 14134 – Service Update Bulletin - OBDII Noncompliance - Misfire Detection - Service Bulletin Attached

GM CUSTOMER CARE AND AFTERSALES
DCS3199
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 29, 2014

Subject: 14134 – Service Update Bulletin
OBDII Noncompliance - Misfire Detection
Service Bulletin Attached

Models: 2014 Chevrolet Cruze
Equipped with Manual Transmission (RPO LUV)


To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, New Vehicle Sales Manager, and Warranty Administrator

The bulletin for this service update was inadvertently not attached to the previous dealer message. Please see the attached bulletin for details.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 14134 Bulletin.pdf Acrobat PDF (96.48KB)
14134 Bulletin

| | |
|---|--------------------|
| Contact name: | E-Mail: j |
| Department: Service - Brand Quality | Phone: |
| Intended roles: General Manager, New Vehicle Sales Manager, Parts & Service Director, Parts Manager, Service Advisor, Service Manager, Warranty Administrator | |
| Archives: 10/29/2014 | Expires: 4/29/2015 |