
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Friday, May 16, 2014 5:06 PM
To: V^:
Subject: internal notification for: G_0000192111 14067A - Safety Recall - Diesel Fuel Transfer Pump Tube Nut Torque - Customer Letter Added
Attachments: 14067A bulletin.pdf

Date: 5/16/2014 Ref. number: Service / Field Action / G_0000192111
Subject: **14067A - Safety Recall - Diesel Fuel Transfer Pump Tube Nut Torque - Customer Letter Added**

GM CUSTOMER CARE AND AFTERSALES
DCS3236
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 16, 2014

Subject: 14067A – Safety Recall
Diesel Fuel Transfer Pump Tube Nut Torque
Customer Letter Added

Models: 2015 Chevrolet Silverado and GMC Sierra HD Equipped with
Diesel Engine (LML) and Dual Fuel Tanks (N2N)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
and Warranty Administrator

Bulletin 14067A has been revised to include a copy of the customer letter. Please discard all copies of bulletin 14067.

Customer Letter Mailing

The customer letter mailing will begin on May 29, 2014.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 [14067A bulletin.pdf](#) Acrobat PDF (234.2KB)
14067A bulletin

Contact name:

E-Mail: