
From: gm_gmssg_q01 <nobody@gm.com>
Sent: Tuesday, May 27, 2014 2:53 PM
To: "
Subject: Internal notification for: G_0000192755 Noncompliance Recalls 14082C and 14105B - Passenger Side Instrument Panel Performance - Revised
Attachments: 14082C bulletin.pdf; 14105B bulletin.pdf

Date: 5/27/2014 Ref. number: Service / Field Action / G_0000192755
Subject: **Noncompliance Recalls 14082C and 14105B - Passenger Side Instrument Panel Performance - Revised**

GM CUSTOMER CARE AND AFTERSALES
DCS3249
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 27, 2014

Subject: Noncompliance Recalls 14082C and 14105B – Revised
Passenger Side Instrument Panel Performance
Revised Service Procedure

Models: 2009-14 Chevrolet Express and GMC Savana Equipped with Front
Passenger Side Airbag (AK5)

To: All Chevrolet and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

Step 3 of the service procedures have been revised. Please discard all copies of bulletins 14082B and 14105A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES

Message Attachment(s):

 14082C bulletin.pdf Acrobat PDF (466.1KB)
14082C bulletin

 14105B bulletin.pdf Acrobat PDF (746.9KB)
14105B bulletin

Contact name
Department: Service - Brand Quality

E-Mail:
Phone: