



NUMBER: 08-039-14

GROUP: Electrical

DATE: April 10, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THE wiTECH SOFTWARE LEVEL MUST BE AT RELEASE 14.03 OR HIGHER TO PERFORM THIS PROCEDURE.

SUBJECT:

The Personal Setting Menu Is Missing The DRL Enable/Disable Option

OVERVIEW:

This bulletin involves reconfiguring the vehicle, to add Daytime Running Lamps (DRL) to the menu for personal settings.

MODELS:

2013-2014 (ZD)

Viper (U.S. and Mexico Only)

NOTE: This bulletin applies to vehicles built on or after December 18, 2012 (MDH 1218XX) on or before October 25, 2013 (MDH 1025XX).

SYMPTOM/CONDITION:

The customer may notice that the personal setting menu doesn't have the option to enable/disable the DRL.

DIAGNOSIS:

Using a Scan Tool (wiTECH™) with the appropriate Diagnostic Procedures available in TechCONNECT, verify no DTC's are set. If DTC's are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom, perform the Repair Procedure.

REPAIR PROCEDURE:

1. Using wiTECH, reconfigure the vehicle. This routine is available under the 'Diagnostic Procedures' tab found on the home, 'Vehicle View', page of wiTECH.
2. Using wiTECH clear any DTCs which may have been set during the reconfiguration.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
18-19-02-H9	Reconfigure Vehicle (1- Semi-Skilled)	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------