

**UPDATE PRIOR TO SALE UPS4114-3B:
 POTENTIAL TRANSMISSION FILTER
 DETACHMENT FROM OIL PAN - UPDATE**

**SERVICE
 BULLETIN**

08-DEC-14 | **NO.: 6-233NAS** | **SECTION: GENERAL** | **MARKET: CAN / USA**
 [issue 2] | **INFORMATION**

*CHANGES ARE LIMITED TO THE EXTENSION OF THE EXPIRY DATE
 AND AN UPDATE TO THE LIST OF AFFECTED VINS*

DESCRIPTION

An issue has been identified on a number of 2015 model year F-TYPE (X152) and 2014 model year XF (X250) and XJ (X351) vehicles within the listed VIN ranges where the transmission filter may become detached from the transmission oil pan base.

AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

- F-TYPE (X152) K11775-K12045
- XF (X250) U29660-U31713
- XJ (X351) V69257-V69749

See the attached list (updated 04 December 2014) for specific VINs.

ACTION TO BE TAKEN

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles within your control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action.

Refer to Technical Bulletin **UPS4114-3bNAS**: *Potential Transmission Filter Detachment from Fluid Pan*, for detailed repair instructions.

PARTS

*** NOTE: when ordering parts, order only the expected percentage demand of parts identified**

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE**	EXPECTED % OF VEHICLES REQUIRING PARTS*
Transmission oil pan kit	JDE36541	1	100
Transmission oil	ZZZ999	£150.00	100

** - an allowance equivalent to US\$244.50 (approximately £150.00) has been provided to cover the cost of the transmission oil.

TOOLS

Refer to Service Instruction / Repair Procedure for any required tools

WARRANTY

NOTE: Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action.

Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**K238**' along with the relevant Option Code. SRO and parts information is included for information only. The drive in / drive out allowance may only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **09 July 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS / SUNDRY CODE	QTY. / VALUE*
K238	B	Install the new transmission fluid pan kit - F-TYPE (X152)	44.24.04	1.90	JDE36541 ZZZ999	1 £150.00
K238	C	Install the new transmission fluid pan kit - F-TYPE (X152) Drive in/drive out	44.24.04 10.10.10	1.90 0.1	JDE36541 ZZZ999 -	1 £150.00 -
K238	B	Install the new transmission fluid pan kit - XF (X250) 3.0L SC V6 RWD	44.24.04	1.20	JDE36541 ZZZ999	1 £150.00
K238	C	Install the new transmission fluid pan kit - XF (X250) 3.0L SC V6 RWD Drive in/drive out	44.24.04 10.10.10	1.20 0.10	JDE36541 ZZZ999 -	1 £150.00 -
K238	B	Install the new transmission fluid pan kit - XF (X250) 3.0L SC V6 AWD	44.24.04	1.40	JDE36541 ZZZ999	1 £150.00
K238	C	Install the new transmission fluid pan kit - XF (X250) 3.0L SC V6 AWD Drive in/drive out	44.24.04 10.10.10	1.40 0.10	JDE36541 ZZZ999 -	1 £150.00 -
K238	B	Install the new transmission fluid pan kit - XF (X250) 5.0L SC V8	44.24.04	1.60	JDE36541 ZZZ999	1 £150.00
K238	C	Install the new transmission fluid pan kit - XF (X250) 5.0L SC V8 Drive in/drive out	44.24.04 10.10.10	1.60 0.10	JDE36541 ZZZ999 -	1 £150.00 -
K238	B	Install the new transmission fluid pan kit - XJ (X351) 3.0L SC V6 AWD	44.24.04	1.60	JDE36541 ZZZ999	1 £150.00
K238	C	Install the new transmission fluid pan kit - XJ (X351) 3.0L SC V6 AWD Drive in/drive out	44.24.04 10.10.10	1.60 0.10	JDE36541 ZZZ999 -	1 £150.00 -

* - an allowance equivalent to US\$244.50 (approximately £150.00) has been provided to cover the cost of the transmission oil.

Normal Warranty policies and procedures apply

UPS4114: AFFECTED VIN LIST- UPDATED
04-DEC-14

CANADA

VIN	Retailer Number / Name
K11779	4498 Jaguar Thornhill
U30371	4498 Jaguar Thornhill

USA

F-TYPE (X152)	
K11979	5311 Jaguar Monmouth
K11982	5703 Galpin Jaguar
K11983	5605 Jaguar West Chester
K11998	5726 Paretti Jaguar of Baton Rouge
K12038	5756 Imperial Motors Jaguar of Lake Bluff
XF (X250)	
U29660	0696 Alpine Jaguar
U29678	5628 Jaguar Newport Beach
U31245	5743 Jaguar Merriam
U31268	5322 Jaguar Birmingham
U31294	5504 Brown's Jaguar
U31310	5774 Jaguar Westside
U31326	5756 Imperial Motors Jaguar of Lake Bluff
U31334	5427 Madison Jaguar
U31342	5796 Jaguar Des Moines
U31350	5302 Jaguar Paramus
U31361	5793 Jaguar Charleston
U31374	5302 Jaguar Paramus
U31382	5302 Jaguar Paramus
U31390	5396 Jaguar Cincinnati
U31442	5725 Manhattan Jaguar/NYC
U31609	5759 Bobby Rahal Jaguar
XJ (X351)	
V69651	0078 Stevinson Imports, Inc.
V69683	5605 Jaguar West Chester
V69749	1459 Howard Orloff Jaguar/Volvo