

NUMBER: 23-027-14

GROUP: Body

DATE: October 01, 2014

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler Group LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 14-080. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Zinc Coating Missing From Left Rear Close Out Panel

OVERVIEW:

This bulletin involves inspecting the Julian date on the left rear close out panel.

MODELS:

2015 (JK) Wrangler

NOTE: This bulletin applies to vehicles built on or after July 29, 2014 (MDH 0729XX) and on or before July 31, 2014 (MDH 0731XX).

SYMPTOM/CONDITION:

Zinc coating missing from left rear close out panel, no corrosion protection.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

REPAIR PROCEDURE:

1. On the left rear corner of the vehicle, behind the wheel, next to the frame, using a flash light, look in the hole identified in (Fig. 1).
2. Inspect the Julian date on the left rear close out panel (Fig. 1) and (Fig. 2).
3. Was the Julian date 205 ? (Fig. 2)
 - a. YES>>> Contact your Area Manager or Business Center Customer Relations/Warranty Manager for buy back instructions.
 - b. NO>>> This bulletin does not apply. Return vehicle to stock or customer.




Fig. 1 Left Rear Close Out Panel Inspection




Fig. 2 Julian Date

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-85-84-90	Inspect The Julian Date On The Left Rear Close Out Panel (0 - Unskilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------