


Reference	SSM71857
Models	Range Rover Evoque / L538
Title	9hp transmission fixings
Category	Driveline
Last modified	20-May-2014 00:00:00
Symptom	501000 Automatic Transmission Concerns
Content	<p><u>Issue:</u> During the replacement of a 9hp 9speed transmissions (Currently fitted to L538 'Evoque' vehicles), It has been highlighted through incomplete warranty claims that not all of the necessary components are being replaced.</p> <p><u>Cause:</u> Technicians are not carrying out repairs as per Topix procedure and re-using old fixings where it is not suitable to do so. One example of this would be the 'Flex plate' to 'Torque Converter' nuts, topix clearly states that new nuts must be installed.</p> <p><u>Repair:</u> We would like this SSM to serve as a general reminder to all technicians that Topix procedures must be followed at all stages. Wherever caution symbols are visible such as:</p> <p> Make sure that new nuts are installed</p> <p>It is imperative that these actions are taken to prevent future component failures.</p>