

Technical Service Bulletin

46 Squeal from front brakes (non-hybrid vehicles)_2.0T with PR-1LB

46 14 82 2037029/2 May 8, 2014. Supersedes Technical Service Bulletin Group 46 number 14-80 dated April 23, 2014 for reasons listed below.

Model(s)	Year VIN Range		Vehicle-Specific Equipment	
Q5	2013 - 2014	Specific VINs; check Elsa	2.0T	

Condition

REVISION HI	EVISION HISTORY		
Revision	Date	Purpose	
2	-	Revised Warranty (Changed Service Number)	
1	4/23/2014	Initial publication	

Customer may report hearing brake noise when the vehicle comes to a stop.

Technical Background

Not applicable.

Production Solution

Improved front brake pads.

Service

Replace the front brake pads according to the instructions in Elsa at: *Repair manual >> Chassis >> 46 Mechanical Components >> Removal and Installation >> Brake Pads, Front >> Brake Pads, 1LB/1LC/1LE/1LP.*

© 2014 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Warranty

Claim Type:	Use applicable claim type. If vehicle is outside any warranty, this Technical Service Bulletin is informational only.				
Service Number:	4617				
Damage Code:	0020				
Labor Operations:	2 Wheels remove & reinstall	4405 2000	20 TU		
	Brake pads, front remove & reinstall	4636 2050	50 TU		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		
	Technical diagnosis at dealer's discretion				
	(Refer to Section 2.2.1.2 and Audi Warranty Online for DADP allowance details)				
Claim Comment:	As per TSB #2037029/2				

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
8R0698151L	1 set of brake pads for disc brakes	1
8R0615121A	Contact (wear sensor)	1

Additional Information

All parts and service references provided in this TSB (2037029) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.

© 2014 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.