

# Technical Service Bulletin



## 94 Cap for dash panel backlight dimming control knob is missing

94 14 51 2038131/1 August 15, 2014.

| Model(s) | Year        | VIN Range | Vehicle-Specific Equipment |
|----------|-------------|-----------|----------------------------|
| A3       | 2015 - 2017 | All       | Not Applicable             |

## Condition

The cap on the control knob for the dash panel backlight dimming switch has fallen off or is damaged (Figure 1).



*Figure 1. Control knob with missing cap*

## Technical Background

This cap was designed to break away under impact.

## Production Solution

Not applicable.

## Service

It is not necessary to replace the complete light switch assembly. The missing cap can be replaced separately.

## Warranty

This TSB is informational only and is not applicable to any Audi warranty.

# Technical Service Bulletin

---



## Required Parts and Tools

| Part Number | Part Description                         | Quantity |
|-------------|--|----------|
| 8V0941158A  | Cap for dash panel lighting control knob | 1        |

## Additional Information

All parts and service references provided in this TSB (2038131) are subject to change and/or removal. Always check with your Parts Department and service manuals for the latest information.