



# Tech Tips

TT 40-13-01

Date: April 26, 2013

2012-2014 CC, Eos, Golf/GTI, Jetta, Jetta Sportwagen, Passat, Tiguan – CV Boot Leaking Grease, Clamp Not Tight or Not Aligned Properly

**March 14, 2014: Update to Information.**

If a CV boot is found to be leaking grease on PDI and a clamp is found to be loose or not aligned properly, only the clamp should be replaced. If concern is found after the vehicle is sold, replace the complete CV joint.