



# Service Bulletin

File in Section: -

Bulletin No.: PIP5134B

Date: November, 2014

## PRELIMINARY INFORMATION

**Subject:** 2014 Chevrolet Cruze Diesel NOX 1 Sensor - Part Restriction

**Models:** 2014 Chevrolet Cruze  
Equipped with the 2.0L (RPO-LUZ) 4-cyl Diesel Engine

**This PI was superseded to update Part Restriction Part Number. Please discard PIP5134A.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

As part of our ongoing quality improvement efforts the 2014 Chevrolet Cruze equipped with the 2.0L Diesel engine (RPO LUZ) NOX 1 Sensor part numbers 12641556 and 12662658 will be placed on a parts restriction through the Product Quality Center (PQC). This parts restriction will assist Engineering with product feedback.

### Recommendation/Instructions

If you require a NOX 1 Sensor for a 2014 Chevrolet Cruze equipped with the 2.0L Diesel engine (RPO LUZ), please complete the diagnostic questionnaire before you contact the PQC at 1-866-654-7654.

Technician's Name/Direct Phone:

Is the restricted part being requested for customer pay?

Customer's concern:

List all DTCs:

Are the current (active) DTCs repeatable?

Has a Charge Air Cooler Diagnosis (Induction System Smoke Test) been performed?

If a leak was found during Charge Air Cooler Diagnosis – please note where the leak is.

Is there a Diesel Exhaust Fluid Warning Message on the Driver Information Center (DIC)?

What is the actual wording of the message?

Has a Reductant Fluid Quality Test been Performed?

Has this vehicle had a history of repair involving the DEF Injector, DEF Fluid Replacement, Diesel Exhaust Fluid Warning Message on the Driver Information Center (DIC) or Nox sensors?

Is the condition temperature related?

If yes, under what conditions?

Is the condition drive cycle related?

If yes, under what conditions?

Have you completed the appropriate SI documents for the DTCs listed?

What SI documents were used for diagnosis?

Using the SI document listed above, list all answers to all steps that were followed in the Circuit/System Testing section

What step in the SI document led to replacement of the NOX 1 sensor?

Is the vehicle modified/non-production accessories? Yes/No

Was TAC contacted? Yes/No

If Yes, TAC Case#:

If applicable, what was TAC agent's recommendation?

The PQC agent may request a picture of the NOX 1 Sensor. The picture would be used as a visual aid in determining carbon (soot) build up.

If requested, email the picture to [GMPartRestriction@gmexpert.com](mailto:GMPartRestriction@gmexpert.com), with the dealer's BAC code and the PQC case number in the email title line.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.