



# Service Bulletin

File in Section: -

Bulletin No.: PIP5154A

Date: April, 2014

## PRELIMINARY INFORMATION

**Subject:** 2014 Chevrolet Corvette 6.2L - LT1 - Engine Exchange Has Ended

**Models:** 2014 Chevrolet Corvette  
Equipped with 6.2L Engine (RPO LT1)

**This PI was superseded to end the engine exchange. Please discard PIP5154.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

The 2014 Chevrolet Corvette 6.2L (LT1) Engine Exchange has ended.

The 6.2L Engine (RPO LT1) can now be repaired as needed or can be ordered through the regular CCA parts process.

For ordering dry sump engines use Part Number 12657248.

For ordering wet sump engines use Part Number 12657236.

### Recommendation/Instructions

GM Engineering would like to thank all dealers that participated in this parts restriction.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.