



# Service Bulletin

File in Section: -

Bulletin No.: PIP5185

Date: March, 2014

## PRELIMINARY INFORMATION

**Subject:** Rattle Or Flutter Noise When Switching To And From V4 To V8 Mode

**Models:** 2014 Chevrolet Corvette  
Equipped with engine RPO LT1 6.2L

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

A vehicle may have a concern with a rattle noise at 30 to 40 MPH when the engine is switching between V8 and V4. The concern may only happen when driving and cannot be duplicated the shop.

### Recommendation/Instructions

Inspect the drive belt tensioner for a hydraulic fluid leak.

Only replace the tensioner if it is found to be leaking, then re-evaluate the concern.

### Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4063110	Drive Belt Tensioner Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.