



Service Bulletin

File in Section: -

Bulletin No.: PI1065A

Date: March, 2014

PRELIMINARY INFORMATION

Subject: Program Cluster Message and/or Random Warning Messages Displaying in Driver Information Center (DIC)

Models: 2013-2014 Chevrolet Volt

This PI has been revised to add the 2014 Model Year and provide the field fix. Please discard PI1065.

Condition/Concern

Some customers may comment on a "Program Cluster" message and/or random warning messages displaying in the driver information center (DIC). These messages may intermittently pop-up or display.

This condition may be caused by a software anomaly within the instrument cluster (IPC).

Recommendation/Instructions

An updated software calibration has been released to address this concern. Reprogram the instrument cluster (IPC) using the Service Programming System (SPS) with the latest calibrations available on TIS2WEB. Refer to the Instrument Cluster Programming and Setup procedure in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time