



Service Bulletin

File in Section: -

Bulletin No.: PI1146A

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Missing Automatic Headlamp Control from Turn Signal Switch After Accessories Fog Lamp Kit Install

Models: 2014-2015 Chevrolet Spark
Equipped with Accessory Fog Lamp Kit (RPO S3U)

This PI has been revised to update the Condition/Concern, Parts Information and add the 2015 Model Year. Please discard PI1146.

Condition/Concern

Some technicians may notice that the auto headlamp control is missing from the turn signal switch after an accessory fog lamp kit (part number 95437098 or 95940389) was installed.

This may be due to the fog lamp accessory kit not containing the new turn signal for the 2014 and 2015 model year.

Recommendation/Instructions

Replace the turn signal switch with the part numbers provided below. Refer to Turn Signal Switch Replacement in SI.

Parts Information

Part Number	Description
95242645	Turn Signal Switch Assembly
96224564	Harness Strap

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
0580048*	Turn Signal Switch Installation	0.0 hr

*This is a unique labor operation for bulletin use to cover part cost only. The required labor is included in 0510972 for the LPO accessory and included in the customer paid installation cost when installed as an ACO.