



Service Bulletin

File in Section: -

Bulletin No.: PI1175

Date: February, 2014

PRELIMINARY INFORMATION

Subject: Starter or Flywheel Knock Noise on Start Up

Models: 2012-2013 Chevrolet Cruze
Equipped with 1.8L Engine and Manual Transmission
Built Prior to January 10, 2014

Condition/Concern

Some customers may comment on a knock noise coming from the front of the vehicle on start up. This may be caused by the starter not having a high enough cranking speed.

Recommendation/Instructions

Technicians should replace the starter and the fuse block. Refer to Starter Replacement (1.8L LUW and LWE) and Fuse Block Replacement in SI.

Parts Information

Part Number	Description
55572439*	STARTER
95937484*	BLOCK FUSE

*These parts are on restriction. The PQC must be contacted prior to ordering.

Warranty Information

For vehicles repaired under warranty, use:

Note: Dealers should use Complaint Code 0343 Transmission — Transmission Noise.

Labor Operation	Description	Labor Time
8480068*	Replace Starter Motor and Fuse Block	0.7 hr

*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.