



Service Bulletin

File in Section: -

Bulletin No.: PIP5242A

Date: December, 2014

PRELIMINARY INFORMATION

Subject: Squeak Noise Heard When Operating Clutch Pedal

Models: 2011-2015 Chevrolet Cruze
With manual transmission M32

This PI was superseded to update Model Years. Please discard PIP5242.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Some customers may comment on a squeak noise when operating the clutch pedal. This condition may be due to incompatibility between the plastic pivot pin and the plastic clutch pedal.

Recommendation/Instructions

Please contact GM TAC if you are working on a 2010-2015 Chevrolet Cruze (with manual transmission M32) with the concern of a squeak noise when operating the clutch pedal.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.