



# Service Bulletin

File in Section: -

Bulletin No.: PIT5296

Date: June, 2014

## PRELIMINARY INFORMATION

**Subject:** Creak Or Pop Type Noise From Right Front Body During At Slow Speeds Driving

**Models:** 2014 Chevrolet Equinox  
2014 GMC Terrain  
Built Between 02/01/14 and 05/31/14

### Condition/Concern

Customers may comment on a right front creak or pop type noise during slow speed body twist driving maneuvers. Raising the vehicle with a floor jack on the right front control arm may also create this noise condition.

### Recommendation/Instructions

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating this concern. This PI will be updated with additional details as they become available.