



SERVICE BULLETIN

Update Prior to Sale Notice UPS4413: Anti-Lock Brake, Climate Control, and Parking Aid Control Module Software Update

06-MAR-14	No.: SGI13-19 (issue 2)	Section: GENERAL INFORMATION	Market: CAN / USA
-----------	----------------------------	---------------------------------	-------------------

CHANGES ARE HIGHLIGHTED IN GRAY

DESCRIPTION

To ensure 2014 model year Range Rover (L405) vehicles are equipped with the very latest software, a limited number of vehicles require updates to the following control modules:

- Anti-Lock Brake System (ABS);
- Climate Control;
- Parking Aid System.

AFFECTED VEHICLES

The VIN range of affected vehicles is: EA110440-EA135110

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this Update Prior to Sale notice prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles within the listed VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action.

Refer to Technical Bulletin UPS4413: *Update Prior to Sale: Anti-Lock Brake, Climate Control, and Parking Aid Control Module Software Update*, for detailed repair instructions.


PARTS

No parts required

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY

 **NOTE:** Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Always refer to the Repair Times Searcher (RTS) on TOPIx to obtain the latest repair time. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code '**Q324**' together with the relevant Option Code. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the program's **06 September 2014** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY. / VALUE
Q324	B	VIN EA110440-EA129699 ONLY Update Anti-lock Brake System control module software	70.90.03	0.3	-	-
		Update Parking Aid control module software - with IDS connected	86.90.63.02	0.1	-	-
		Update Climate Control control module software - with IDS connected	80.90.12.02	0.1	-	-
Q324	C	VIN EA110440-EA129699 ONLY Update Anti-lock Brake System control module software	70.90.03	0.3	-	-
		Update Parking Aid control module software - with IDS connected	86.90.63.02	0.1	-	-
		Update Climate Control control module software - with IDS connected	80.90.12.02	0.1	-	-
		Drive in / drive out	02.02.02	0.2	-	-
Q324	F	VIN EA129700-EA131561 ONLY Update Anti-lock Brake System control module software	70.90.03	0.3	-	-
		Update Climate Control control module software - with IDS connected	86.90.63.02	0.1	-	-
Q324	G	VIN EA129700-EA131561 ONLY Update Anti-lock Brake System control module software	70.90.03	0.3	-	-
		Update Climate Control control module software - with IDS connected	86.90.63.02	0.1	-	-
		Drive in / drive out	02.02.02	0.2	-	-
Q324	K	VIN EA131562-EA135110 ONLY Update Climate Control control module software	80.90.12	0.2	-	-
Q324	L	VIN EA131562-EA135110 ONLY Update Climate Control control module software	80.90.12	0.2	-	-
		Drive in / drive out	02.02.02	0.2	-	-

Normal Warranty policies and procedures apply