

Update Prior to Sale Notice UPS5513: Door Interior Release Handle Lamp Operation - Update

SERVICE BULLETIN

17-SEP-14

No.: SGI13-26

Section: GENERAL

Market: CAN / USA

(issue 3)

INFORMATION

CHANGES ARE HIGHLIGHTED IN GRAY

DESCRIPTION

A limited number of 2014 model year Land Rover Range Rover Sport and Range Rover vehicles within the listed VIN range may not have the required power feed to the lamp above the door interior release handles located in each door casing.

AFFECTED VEHICLES

The VIN ranges of affected vehicles are:

Range Rover Sport (L494) EA308085-EA314577
Range Rover (L405) EA133141-EA138212

WORKSHOP PROCEDURES

Retailers are required to check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. Retailers are required to **HOLD** all affected vehicles in the above VIN range that are in their control and refrain from releasing the vehicles for new or used vehicle sale pending completion of the rework action. Affected vehicles already in the hands of customers should be updated at the next available opportunity.

Refer to Technical Bulletin UPS5513-6bNAS: *Update Prior to Sale: Door Interior Release Handle Lamp Operation*, for detailed repair instructions.

PARTS

No parts necessary

TOOLS

Refer to Workshop Manual / Service Instruction for any required tools

WARRANTY



NOTE: Repair procedures are under constant review, and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time. Check DDW to ensure that the vehicle is affected by this program prior to undertaking any rework action. At the time of confirming a booking for vehicle repair, ensure that all outstanding Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting Program Code 'Q336' together with the relevant Option Code from the table. SRO and parts information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought into the workshop for this action alone to be undertaken.

This program is valid for a limited time only. Warranty claims with a repair date prior to the **31 January 2015** closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART No.	QTY.
Q336	В	Check all doors' interior release handle aperture lamp operation; no further action	05.10.20	0.2	-	-
Q336	С	Check all doors' interior release handle aperture lamp operation; no further action	05.10.20	0.2	-	-
		Drive in/drive out	02.02.02	0.2	-	-
Q336	F	Check all doors' interior release handle aperture lamp operation; carry out repair on 1 door handle lamp	05.10.40	0.4	-	-
Q336	G	Check all doors' interior release handle aperture lamp operation; carry out repair on 1 door handle lamp	05.10.40	0.4	-	-
		Drive in/drive out	02.02.02	0.2	-	-
Q336	К	Check all doors' interior release handle aperture lamp operation; carry out repair on 2 door handle lamps	05.10.80	0.8	-	-
Q336	L	Check all doors' interior release handle aperture lamp operation; carry out repair on 2 door handle lamps	05.10.80	0.8	-	-
		Drive in/drive out	02.02.02	0.2	-	-
Q336	Р	Check all doors' interior release handle aperture lamp operation; carry out repair on 3 door handle lamps	05.11.12	1.2	-	-
Q336	Q	Check all doors' interior release handle aperture lamp operation; carry out repair on 3 door handle lamps	05.11.12 02.02.02	1.2	-	-
		Drive in/drive out	02.02.02	0.2	-	-
Q336	Т	Check all doors' interior release handle aperture lamp operation; carry out repair on 4 door handle lamps	05.11.16	1.6	-	-
Q336	V	Check all doors' interior release handle aperture lamp operation; carry out repair on 4 door handle lamps	05.11.16	1.6	-	-
N/2 2 / 14/		Drive in/drive out	02.02.02	0.2	-	-

Normal Warranty policies and procedures apply