



# Service Bulletin

File in Section: -

Bulletin No.: PIT5298

Date: June, 2014

## PRELIMINARY INFORMATION

**Subject:** Installation Of Upfitter Auxiliary Switches (RPO 9L7)

**Models:** 2014 Chevrolet Silverado 1500  
2015 Chevrolet Silverado  
2014 GMC Sierra 1500  
2015 GMC Sierra

### Condition/Concern

A Dealer or Upfitter may be looking for information on installing RPO 9L7 Upfitter Auxiliary Switches. The Upfitter Auxiliary Switches are located under the climate controls in the center of the dash.

### Recommendation/Instructions

Reference the latest version of GM Upfitter Integration Bulletin 110. The information can be found at <http://www.gmupfitter.com/>, under the "Technical Bulletin" Tab and then "Show all bulletins."