



Service Bulletin

File in Section: -

Bulletin No.: PIT5315A

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Clarification Of RAP Operation

Models: 2013-2015 Chevrolet Express
2013-2015 GMC Savana
With Radio Provisions Only (RPO UXZ)

**This PI was superseded to update information about installing a factory radio.
Please discard PIT5315.**

Some owners may comment that their RAP (retained accessory power) feature is inoperative after turning the ignition key off and before opening any door

If the vehicle is equipped with radio provisions but was NOT built with a radio, the RAP feature will not be present.

If the vehicle is equipped with power windows and radio provisions but was NOT built with a radio, the power windows will be disabled after the ignition key is turned off.

If a GM radio approved for these vehicles is installed at a later date, the RAP feature will then be functional

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Important: Once installed, the radio will need to be programmed with software available in TIS2WEB.