File in Section:

Bulletin No.: PIT5357

Date: December, 2014

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: VIS / GWM / IVH May Not Match Actual Audio System of Vehicle

Models: 2015 Chevrolet Colorado

2015 GMC Canyon With Radio RPO IO6

Condition/Concern

In some cases, it may be found that some GM computer systems (IVH / VIS / GWM, etc.) do not properly show the correct audio system of the vehicle.

Recommendation/Instructions

Please refer to the SPID label located in the glove box to verify the correct audio amplifier configuration to ensure correct schematics and diagnostics are followed.