



Service Bulletin

File in Section: -

Bulletin No.: PI1262

Date: June, 2014

PRELIMINARY INFORMATION


Subject: Noise Heard from Center Console

Models: 2014 Chevrolet Silverado 1500
2014 GMC Sierra 1500

Condition/Concern

Some customers may comment on a noise heard from the center console.
This condition may be caused by a plastic burr on the center console retainer.

Recommendation/Instructions



3925866

Modify the retainer using a file to remove the parting line as shown in the illustration above.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
1080158*	File Parting Line On Center Console Retainer	0.3 hr
*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.		