



# Service Bulletin

File in Section: -

Bulletin No.: PI1313

Date: September, 2014

## PRELIMINARY INFORMATION

**Subject:** Automatic Headlamp Transition Time Excessive From Day to Night

**Models:** 2014 Cadillac ATS, CTS Sedan (VIN A) (Export Europe Only)

### Condition/Concern

Some customers may comment that it takes too long (approximately 20 seconds) for the automatic headlamps to transition from day to night when entering a tunnel or parking garage.

### Recommendation/Instructions

An updated software calibration has been released to address this concern. Reprogram the body control module (BCM) using the Service Programming System (SPS). The calibration must be requested by email at SPS team@gm.com. Please include the following information in the email.

- VIN
- The module that needs to be updated
- PI/Bulletin/Campaign #
- Specific request (what they are asking for)

All requests need to be submitted in English. If it cannot be submitted in English, please contact your local helpdesk/importer.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2810215	Body Control Module Reprogramming with SPS	Use Published Labor Operation Time