

Reference	SSM71438
Models	LR4 / L319 Range Rover / L322 Range Rover Sport / L320
Title	oil leak from transfer case output flange - 2008 to 2010 Model Year
Category	Driveline
Last modified	24-Jan-2014 00:00:00
Symptom	508000 Transfer Case Concerns
Content	Issue: Oil leak from transfer case output flange Cause: The cause is under investigation Action: Engineering is investigating oil leaks from the transfer case output flange on the following vehicles only: 2008 to 2010 Model Years - Discovery 4 (LR4), Range Rover, and Range Rover Sport. Although this issue can be repaired, the engineers would like to get a small number of transfer cases returned to the supplier so the cause of the leak can be fully investigated. Where the customer will not be troubled, please report this issue using an EPQR. Pictures of the issue should be included. The information will be reviewed by the engineer, who will make a decision if the transfer case assembly should be replaced or if the flange should be repaired. A Priority Return Request will be raised where required.