

Valve Block Parts Breakdown (1).pdf

Reference	SSM71484
Models	Range Rover Sport / L320
Title	Dynamic Response Valve Block Lower Level Components Available
Category	Chassis
Last modified	03-Feb-2014 00:00:00
Symptom	304000 Suspension System
Content	<p><u>Issue:</u> A customer may complain that the dynamic response lamp is illuminated and diagnostic trouble codes (DTC) C1119-09,C1119-22,C1119-62, C1119-91,C1B11-62, may be present.</p> <p><u>Cause:</u> Replacement of the valve block may not be required as lower level components are available. See attached document for component location and part numbers.</p> <p><u>Action:</u> Please refer to TOPIx Section 100-00 General Information, DTC: Dynamic Response Module (ARCM) for possible DTC causes and actions which have recently been amended.</p>

RVH500110

3137

RVT500010

9R299A

9R299A

RQH500020

5359

RVH500100

5B321

RVT100021

9R299B

5F483

100%

7D302

HW1

HB1

HB1

HW1

HW1

HN1

RVJ100010

HW1

HB1

6A768

HW1

HN1

5D087

HW1

HN1

DMS



Unable to connect to the DMSi. Check the parameters and ensure that the DMSi is running.

Done