



# Service Bulletin

File in Section: -

Bulletin No.: PIC5205D

Date: December, 2014

## PRELIMINARY INFORMATION

**Subject:** Normal Characteristic - Radio Display Fogs Up When Using Air Conditioning

**Models:** 2010 - 2015 Chevrolet Camaro

**This PI was superseded to update Model Years and Omit Administrative Details.  
Please discard PIC5205C.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

Some customers may comment that portions of the radio display fogs up when using the Air Conditioning. This will typically occur during the following conditions:

1. When the blower speed is placed to the HIGH position.
2. When the center vents are pointed downward toward the radio display.

### Recommendation/Instructions

**Important:** Do NOT replace any parts for this concern.

Do NOT replace any parts for this concern.

This condition can be reduced or eliminated by not pointing the center IP HVAC vents down toward the radio and, once the vehicle interior has cooled off, it is suggested to decrease the blower speed.

### Customer Information

Please communicate to the customer this condition is a normal operating characteristic of their vehicle. This condition will not impact the designed performance or reliability of the vehicle. Please share this information with the customer, including a copy of this message.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.