



# Service Bulletin

File in Section: -

Bulletin No.: PIC5934A

Date: March, 2014

## PRELIMINARY INFORMATION

**Subject:** Intermittently Radio Display Has Flickering Or Rolling Image

**Models:** 2014 Chevrolet Corvette Stingray

**This PI was superseded to advise dealers to contact TAC. Please discard PIC5934.**

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

### Condition/Concern

On rare occasions, a customer or dealer may comment that the radio display is blinking, flickering, rolling, or scrolling. Typical comments are that it looks like an old TV with a rolling image and that raising or lowering the display may make the concern come and go.

### Recommendation/Instructions

Please contact the GM Technical Assistance Center at (877) 446-8227 (US Dealers) or (800) 263-7740 (Canadian Dealers) to review the latest repair suggestions.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.