



Service Bulletin

File in Section: -

Bulletin No.: PIC6046

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Diagnostic Tip - Clock May Be Inaccurate at Times

Models: 2013-2015 Chevrolet Sonic, Spark, Trax
Equipped with MyLink Radio (UF7)

Condition/Concern

The customer may comment that the time on the radio display is inaccurate at times

If the clock is set to "automatically update" the radio will receive time from the FM radio station that the customer is listening to.

If the radio station is broadcasting the incorrect time, the incorrect time will be displayed on the radio as well.

Recommendation/Instructions

If this concern is encountered, it can be alleviated by turning off the Automatic Clock Sync feature by selecting Home> Settings> Time and Date Settings> Automatic Clock Sync.

Note: Be advised that the time will have to be kept current manually and will not adjust for Daylight Savings Time if this feature is turned off. Please relay this to the customer.