



# Service Bulletin

File in Section: -

Bulletin No.: PIC6054

Date: December, 2014

## PRELIMINARY INFORMATION

**Subject:** Delayed Radio Display Operation When First Starting Vehicle at Times

**Models:** 2014-2015 Cadillac XTS

### Condition/Concern

Customer may comment that the radio display has a delay to turn on after starting the vehicle. Audio and Steering wheel controls still function when concern is present.

### Recommendation/Instructions

Please do not replace any parts or make any repairs. General Motors is currently working on a solution for this concern.

### Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.