



Service Bulletin

File in Section: -

Bulletin No.: PIC6057

Date: December, 2014

PRELIMINARY INFORMATION

Subject: Navigation Shows Vehicle In Wrong Location

Models: 2015 Buick Encore, Verano
2015 Chevrolet Camaro, Cruze, Equinox, Malibu, Orlando (Canada Only), Volt
2015 GMC Terrain
Equipped with Radio RPOs UHK, UHR, UHJ, or UHQ

Condition/Concern

Customer may comment that the vehicles location on the navigation display is off by up to a quarter of a mile.

Recommendation/Instructions

Please do not replace any parts for this concern. This concern can usually be resolved by an ignition cycle. Engineering is currently looking into a solution and the PI will be updated when a solution is available.

Customer Information

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. In the meantime, this concern can usually be resolved by cycling the ignition. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.