



Service Bulletin

File in Section: -

Bulletin No.: PI1331A

Date: November, 2014

PRELIMINARY INFORMATION

Subject: Incorrect Icon for Power Assist Step/Running Board Switch

Models: 2015 Chevrolet Suburban, Tahoe
2015 GMC Yukon Models
Equipped with RPOs BRS, JF4, UFL (EXC JHD)

This PI has been revised to update the Warranty Information. Please discard PI1331.

Condition/Concern

During PDI Inspection it may be noticed that the multi-switch pod located left of the instrument cluster may be missing the power assist step/running board switch. The typical location for this switch may instead show hill descent control.

Some vehicles may have been built with the correct switch part number but produced with the wrong icon for the power assist step/running board button as shown below.

①



Legend

(1) Incorrect Icon

3995324

②



3995325

Legend

(2) Correct Icon

Only the VINs listed below may be affected.

| VIN LIST | | |
|-------------------|-------------------|-------------------|
| 1GKS27KJXFR277149 | 1GKS2CKJ0FR277864 | 1GKS2CKJ1FR277419 |
| 1GKS2CKJ2FR277624 | 1GKS2CKJ3FR278006 | 1GKS2CKJ4FR277267 |
| 1GKS2CKJ4FR277351 | 1GKS2CKJ4FR277432 | 1GKS2JKJ0FR278565 |
| 1GKS2JKJXFR277391 | 1GNSKCKC0FR277822 | 1GNSKCKC1FR277375 |
| 1GNSKCKC1FR277389 | 1GNSKCKC1FR277554 | 1GNSKCKC1FR277618 |
| 1GNSKCKC3FR277104 | 1GNSKCKC4FR277211 | 1GNSKCKC6FR277713 |
| 1GNSKCKC6FR277789 | 1GNSKCKC7FR277977 | 1GNSKCKCXFR278542 |
| 1GNSKCKC8FR277518 | 1GNSKCKC9FR278158 | |

Recommendation/Instructions

If identified as having an incorrect icon, technicians should replace the switch pod using the part number listed below. Refer to Vehicle Stability Control System Switch Replacement in SI.

Parts Information

| Part Number | Description |
|-------------|-----------------------------------|
| 22827588 | SWITCH ASM-VEH STABILITY CONT SYS |

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time |
|-----------------|---|------------------------------------|
| 2410900 | Vehicle Stability Control System Switch Replacement | Use Published Labor Operation Time |