

Reference	SSM70018
Models	F-TYPE / X152 XJ / X351 XF / X250
Title	Transmission DTC P0780-94
Category	Driveability
Last modified	25-Mar-2014 00:00:00
Symptom	698298 Malfunction Indicator Lamp
Content	<p><u>Issue:</u> A Customer may report that their Transmission rotary shifter or Gear selector may be either locked, or failing to engage drive or reverse.</p> <p><u>Cause:</u> An error in the software functionality has been discovered which can create DTC P0780-94.</p> <p><u>Action:</u> JLR are currently working on a software fix to resolve this issue. In the meantime please do not change the Gear Shift Module unit, as this will not resolve the issue.</p> <p>This issue affects - XF 12, 13, 14 & 15 MY XJ 13 & 14 MY F-Type 14 & 15 MY</p>