

Fuel Pipe vibration1.pdf

Reference	SSM68938
Models	XF / X250
Title	XF 2.0 GTDI Rattle/Vibration from front Wheelarch area
Category	Noise Vibration
Last modified	07-Apr-2014 00:00:00
Symptom	703000 Vibration Concerns
Content	<p><u>Issue:</u> A customer may report a "Rattle / Vibration" sound coming from the front left hand wheel arch area of their vehicle.</p> <p><u>Cause:</u> This issue has been indentified as a manufacturing process error where a fuel pipe has been incorrectly routed, and is in contact with the wheel arch body panel.</p> <p><u>Action:</u> Please refer to the attached document which shows the correct routing and clearance of the fuel pipes and reposition where required.</p>



X



✓